

Property Condition Report

Property Address: 1509 Meyer St. Elgin, IL. 60123

Item	Year	Condition	Notes		
Exterior					
Roof	2010				
Windows	UNK				
Siding/Brick	UNK				
Soffits/Fascia/Gutters					
Asphalt/Concrete					

New/Pristine Condition		
Good Condition		
Average Condition		
Poor Condition		

Interior

Heating System	UNK	Electric baseboard Heating
Cooling System	UNK	Window Unit AC
Plumbing	UNK	All Copper piping
Electrical	UNK	Each unit has individual 100 Amp circuit break panel
Water Heater/s	UNK	

Citypoint does not guarantee, warrant, or represent anything contained herein. Information obtained by Citypoint may change during the course of your transaction. Buyer shall conduct its own due diligence regarding financials, expenses, market rents, and the like to determine accuracy of information herein and profitability of transaction. Buyer agrees and acknowledges that Citypoint has made no assurances in relation to any statement or representation made by or on behalf of the Landlord. Citypoint shall not be liable to any party for the declarations set forth herein.